



Drobo B810i Firmware Release Notes

Release Date: Sept 14, 2018

CONTENTS

VERSION INFORMATION
KEY HIGHLIGHTS
KNOWN ISSUES
RELATED TECHNICAL DOCUMENTATION

VERSION INFORMATION

Drobo Firmware: Version 2.0.0 [10.41.104214]

KEY HIGHLIGHTS

This is an update release for B810i. It requires Drobo Dashboard 3.2.0 or later for management.

Fixes in 2.0.0

- Improve stability
- Address issue with timeout on connections in certain configurations

Fixes in 1.3.5

- Bug fixes and performance related issues
- Support for 8TB drives and Samsung SSD 840 EVO

Fixes in 1.3.3

- Bug fix related to upgrade of packs from B800i

Enhancements & Fixes in 1.3.2

- Hyper-V support
- ESXi 6.0 support
- Support migration of diskpack from B800i->B810i
- Stability and performance improvements

Key Features in 1.3.1

- 64 TiB LUN support
- Supports 4KN drives
- Supports Physical tiering and hot data cache using front slot SSDs

KNOWN ISSUES

None

BEST PRACTICES

In accordance with industry best practices, you should always backup your data before any firmware upgrade. For more information, please visit www.drobo.com/support.

Make sure that you keep all software up to date. This includes Drobo Dashboard, which as of this writing the latest release is 3.2.0.

RELATED TECHNICAL DOCUMENTATION

Current Drobo technical reference materials are available on the Drobo Support Website (<http://www.drobo.com/support.html>). This includes:

- *Knowledge Base*
- *Best Practices*
- *Product Documentation*

Copyright 2018 Drobo, Inc. Data Robotics, Drobo, and BeyondRAID are trademarks of Drobo, Inc., which may be registered in some jurisdictions. All other trademarks used are owned by their respective owners. All rights reserved. Specifications subject to change without notice.

P/N 081-00044-001
Rev 01